


Item	Qty.	Description
1	4	38" GS220 Vertical Extrusion
2,2A	1,1	28.66" Curved Horizontal Extrusion
3,3A	1,1	28.66" Curved Horizontal Extrusion
4,4A	1,1	32.225" Curved Horizontal Extrusion
5,5A	1,1	32.225" Curved Horizontal Extrusion
6,6A	2,2	13.5" Horizontal Extrusion
7	1	34.418" Vertical Extrusion w/ Door Stopper
8	1	34.418" Vertical Extrusion w/ Hinges

- Steps:
- 1) Connect curved horizontals [2 to 3] [2A to 3A] [4 to 5] and [4A to 5A].
 - 2) Attach lower horizontals [2/3] [2A/3A] [6] between verticals [1].
 - 3) Attach verticals [7] and [8] to lower horizontal assembly [2/3], with door between.
 - 4) Insert infills between verticals [1], making sure Velcro is facing inward.
 - 5) Connect door to vertical [8]. See [Door Connection](#) detail.
 - 6) Attach upper horizontals [2A/3A] [4A/5A] and [6A] between verticals [1], to secure infills.
 - 7) Attach shelf supports to Velcro on inside of assembled counter then place shelf on top of supports.
 - 8) Place counter top on assembled counter base. See [Counter Top Lock](#) detail.




Completed Counter Assembly

* Door Connection


Slide pin into hinge attached to vertical. Slide door hinge over pin.






* Counter Top Lock



Align hole with pin



Rotate pin. Spring will push pin into hole.



SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts:
Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure.
Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials.
All provided packing materials are for ease of repacking & component protection.

Disassembly


- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering




Spline Connection



Base Plate & Extrusion Connection




Extrusion & Lock Connection



Engaged Lock



WARNING



DO NOT USE POWER TOOLS




LADDERS OR LIFTS
MAY BE REQUIRED




ALL CONNECTIONS MUST
BE TIGHTLY SECURED


Top View of Each Level




Level 1 (Bottom Level)




Level 2




Level 3




Top View of Each Level




Level 1 (Bottom Level)



Level 2



Level 3



Level 4