



Item	Qty.	Description
1	1	38" GS220 Extrusion w/ 34.417" L-Channel
2	1	38" GS220 Extrusion w/ Door Hinges
3	1	38" GS220 Extrusion
4	1	38" GS220 Extrusion
5	2	33.026" Z45 Curved Extrusion
6,6A	1,1	74.815" Z45 Curved Extrusion
7	2	24.813" Z45 Extrusion
8	2	24.813" Z45 Extrusion

- Steps:
- 1) Attach lower extrusions [5] [6] and [7] between vertical extrusions [1] [2] [3] and [4].
 - 2) Slide infills between [1] [2] [3] and [4], making sure Velcro is facing inward.
 - 3) Secure infills with upper extrusions [5] [6A] and [8].
 - 4) Attach door to vertical [2]. See [Door Connection](#) detail.
 - 5) Connect shelf supports to Velcro on infills.
 - 6) Place shelf on top of supports.
 - 7) Lock counter top to extrusions [6A] and [8]. See [Counter Top Lock](#) detail.







Completed Front View



Completed Back View

Keep L-channel attached to extrusion [1].



SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts:
Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure.
Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials.
All provided packing materials are for ease of repacking & component protection.

Disassembly


- For loss prevention, tighten all set screws and locks during disassembly.




Hex Tool - Essential for Assembly




Part Identification - Numbering




Spline Connection



Base Plate & Extrusion Connection



Extrusion & Lock Connection



Engaged Lock



WARNING



DO NOT USE POWER TOOLS



LADDERS OR LIFTS
MAY BE REQUIRED



ALL CONNECTIONS MUST
BE TIGHTLY SECURED